

VACUUM CLEANER EQUIPPED WITH
PIVOTALLY MOUNTED AGITATOR SECTION
Richard E. Downey et al.
380-166 II
Replacement Sheet 1 of 3

Fig. 1





Fig. 3






Fig. 4